

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401974079

Date Received:

03/15/2019

FIR RESOLUTION FORM

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brian Dodek

720-225-6653

bdodek@bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404419

Inspection Date: 01/09/2019

FIR Submit Date: 01/18/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Company Number: 8960

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 452873

Location Name: Mustang Number: U-22 County: _____

Qtrqtr: NENE Sec: 22 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.304675 Longitude: -104.416369

FACILITY - API Number: 05-123- -00 Facility ID: 452873

Facility Name: Mustang Number: U-22

Qtrqtr: NENE Sec: 22 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.304675 Longitude: -104.416369

CORRECTIVE ACTIONS:

1 ☒ CA# 121844

Corrective Action: Comply with Rule 603.f. immediately

Date: _____

Response: CA COMPLETED

Date of Completion: 01/22/2019

Operator
Comment:

Trash was removed. This was not onsite for an extended period of time. The trash was from an ongoing construction project.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 121845

Corrective Action: Comply with Rule 603.f. immediately

Date: _____

Response: CA COMPLETED

Date of Completion: 01/22/2019

Operator Comment: Equipment was installed/removed. This was not onsite for an extended period of time. The equipment was from an ongoing construction project.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 ☒ CA# 121846

Corrective Action: Operator shall immediately implement Best Management Practices per Rule 603.f. to control and manage weeds to prevent weed waste and to prevent the spread of dispersing seeds onto adjacent lands.

Date: _____

Response: CA COMPLETED

Date of Completion: 01/22/2019

Operator Comment: Weeds were removed. Bonanza will monitor and spray as needed moving forward.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

4 ☒ CA# 121848

Corrective Action: Comply with Rule 1002.f.(2) immediately

Date: _____

Response: CA COMPLETED

Date of Completion: 01/25/2019

Operator Comment: Same as below.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

5 ☒ CA# 122016

Corrective Action: Operator shall immediately stabilize cut and fill slopes, and stabilize the well pad to abide by Rule 1002 e.(1), as the location should be in compliance at all times. Long-term well pad stabilization shall be implemented.

Date: _____

Operator shall take measures to comply with Rule 1004 and control wind erosion throughout the impacted deposition areas off Location.

Response: CA COMPLETED

Date of Completion: 01/25/2019

Operator Comment: Removed offsite sediment, stabilized cut/fill slopes. Bonanza implemented soil amendments and seeded as a long term BMP.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: _____

Title: Env ManagerDate: 3/15/2019 12:45:00 PM**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401974079	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files