

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401974106
Date Received:
03/15/2019

FIR RESOLUTION FORM

CA Summary:
3 of 3 CAs from the FIR responded to on this Form
3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Brian Dodek 720-225-6653 bdodek@bonanzacrk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682404421
Inspection Date: 01/09/2019 FIR Submit Date: 01/18/2019 FIR Status:

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 450205

Location Name: Mustang Number: 44-22 Pad County:
Qtrqtr: SESE Sec: 22 Twp: 4N Range: 63W Meridian: 6
Latitude: 40.293817 Longitude: -104.416389

FACILITY - API Number: 05-123-00 Facility ID: 450205

Facility Name: Mustang Number: 44-22 Pad
Qtrqtr: SESE Sec: 22 Twp: 4N Range: 63W Meridian: 6
Latitude: 40.293817 Longitude: -104.416389

CORRECTIVE ACTIIONS:

1 CA# 121849

Corrective Action: Operator shall immediately implement Best Management Practices per Rule 603.f. to control and manage weeds to prevent weed waste and to prevent the spread of dispersing seeds onto adjacent lands. Date:

Response: CA COMPLETED Date of Completion: 01/29/2019

Operator Comment: Weeds were removed

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 CA# 121990

Corrective Action: Comply with Rule 1002.f.(2) immediately Date: _____

Response: CA COMPLETED Date of Completion: 01/25/2019

Operator Comment: Same as below

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

3 CA# 122017

Corrective Action: Operator shall immediately stabilize cut and fill slopes, and stabilize the well pad to abide by Rule 1002 e.(1), as the location should be in compliance at all times. Long-term well pad stabilization shall be implemented. Date: _____

Operator shall take measures to comply with Rule 1004 and control wind erosion throughout the impacted deposition areas off Location.

Response: CA COMPLETED Date of Completion: 01/25/2019

Operator Comment: Removed offsite sediment, stabilized cut/fill slopes. Bonanza implemented soil amendments and seeded as a long term BMP.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek Signed: _____

Title: Env Manager Date: 3/15/2019 12:48:16 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401974106	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files