



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Wellhead sign is missing Ermergency Contact number	Date:	04/19/2019
Corrective Action:	Install sign to comply with Rule 210.b. See Photo #1		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 298332 Type: WELL API Number: 123-29032 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
On 3/18/2019, I Erica Petrie performed an inspection of the Lind 20-24 (Location ID 302373) owned and operated by Great Western Oil & Gas. While on inspection I observed the following issue(s) Wellhead sign missing Emergency Contact Number, see photo 1, Cite 210.b END.	petrie	03/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401976559	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766044">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766044</a>
696300026	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766040">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4766040</a>