

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2018

Submitted Date:

04/01/2019

Document Number:

693900107

FIELD INSPECTION FORM

Loc ID 333333 Inspector Name: ROY, CATHERINE On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 74650
Name of Operator: RIM OPERATING INC
Address: 5 INVERNESS DRIVE EAST
City: ENGLEWOOD State: CO Zip: 80112

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rector, Mike	720-221-1677	mhr@rimop.com	SW Inspection Reports
Ortiz, Liz	303-799-9828 Ext. 304	lortiz@rimop.com	SW Inspection Reports
Elledge, Randy	505-320-4969	relledge@rimop.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271539	WELL	PR	11/15/2005	GW	067-08933	PAYNE 1	RI

General Comment:

[This is an interim reclamation and stormwater inspection.](#)

Inspected Facilities

Facility ID: 271539 Type: WELL API Number: 067-08933 Status: PR Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by irrigated grass field, and is adjacent to two mapped intermittent streams.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment Scattered wood and metal debris observed within the the project area.

Corrective Action Remove debris.

Date **05/01/2019**

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? In Production areas stabilized ?
 1003c. Compacted areas have been cross ripped?
 1003d. Drilling pit closed? Subsidence over on drill pit?
 Cuttings management:
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

1003 f. Weeds Noxious weeds?

Comment

Corrective Action

Date

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA%
 TRANSECT RESULTS OF REFERENCE AREA%
 TOTAL % OF DESIRABLE VEGETATION COVER
 VEGETATIVE COVER

Comment:

Corrective Action:

Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosional channels are present and causing erosion within the southern and eastern portions of the project area.

Corrective Action: Stormwater controls need to be installed to stabilize erosional channels and prevent sediment discharge from the project area.

Date: 05/31/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693900108	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4779701