

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401996729

Date Received:

04/04/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Tesla Dougherty

Phone

970-304-5245

Email

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504529

Inspection Date: 02/27/2019

FIR Submit Date: 02/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 432189

Location Name: TIMBRO FEDERAL LD Number: 07-78HN County: _____

Qtrqr: Lot 1 Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772233 Longitude: -103.915842

FACILITY - API Number: 05-123- -00 Facility ID: 432189

Facility Name: TIMBRO FEDERAL LD Number: 07-78HN

Qtrqr: Lot 1 Sec: 7 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.772233 Longitude: -103.915842

CORRECTIVE ACTIONS:

1 CA# 122780

Corrective Action: Comply with 1002.e and restrict vehicle travel to the designated constructed areas of the pad and access roads to avoid degradation to slopes and interim areas.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/01/2019

Operator Comment: The interim area on the southwest end of the location has been reseeded. Noble has retrained employees on the designated vehicle route to avoid degradation of the surrounding areas.

COGCC Decision: _____

COGCC
Representative:

2 CA# 122781

Corrective Action: Perform reclamation in accordance with COGCC 1000 series rules, remove gravel (and any remaining material not conducive to reclamation) and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 3/31/2019

Date: 03/31/2019

Response: CA COMPLETED

Date of Completion: 04/01/2019

Operator
Comment: Interim reclamation activities were performed on location

COGCC Decision:

COGCC
Representative:

3 CA# 122782

Corrective Action: Install required stormwater and erosion control BMPs in accordance to Rule 1002.f and good engineering practices. Continue BMP maintenance and stormwater management until final reclamation has passed.

Date: 03/31/2019

Response: CA COMPLETED

Date of Completion: 04/01/2019

Operator
Comment: The stormwater BMPs have been fixed around location

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty@nblenergy

Signed: _____

Title: EHS Specialist

Date: 4/4/2019 3:04:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files