

GOLDEN EAGLE 21-10 API# 05-071-08417 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100376



PHOTO 1: LOCATION SIGN

GOLDEN EAGLE 21-10 API# 05-071-08417 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100376



PHOTO 2: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM LOCATION. ALL FITTINGS WERE SECURELY FASTENED TO ENSURE GOOD MECHANICAL CONDITION.

GOLDEN EAGLE 21-10 API# 05-071-08417 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100376



PHOTO 3: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM LOCATION. ALL FITTINGS WERE SECURELY FASTENED TO ENSURE GOOD MECHANICAL CONDITION.

GOLDEN EAGLE 21-10 API# 05-071-08417 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 09, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 695100376



PHOTO 4: THE PACKINGS WERE SECURELY FASTENED TO STOP THE LEAK AND ENSURE GOOD MECHANICAL CONDITION.