

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401996707

Date Received:

04/04/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504533

Inspection Date: 02/27/2019

FIR Submit Date: 02/28/2019

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 433177

Location Name: TIMBRO LD Number: 06-64HN County: _____

Qtrqr: Lot 6 Sec: 6 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.778367 Longitude: -103.916297

FACILITY - API Number: 05-123-00 Facility ID: 433177

Facility Name: TIMBRO LD Number: 06-64HN

Qtrqr: Lot 6 Sec: 6 Twp: 9N Range: 58W Meridian: 6

Latitude: 40.778367 Longitude: -103.916297

CORRECTIVE ACTIONS:

1 ☒ CA# 122783

Corrective Action: Conduct reclamation in accordance with 1000 series rules on the disturbed areas south of the location.

Date: 03/31/2019

Response: CA COMPLETED

Date of Completion: 04/03/2019

Operator Comment: Interim reclamation activities were performed on location

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection. Operator has not provided any documentation attached with this FIRR to

COGCC Representative: indicate or show corrective action has been addressed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 122784

Corrective Action: Install required stormwater and erosion control BMPs in accordance to Rule 1002.f and good engineering practices. Continue BMP maintenance and stormwater management until final reclamation has passed.

Date: 03/31/2019

Response: CA COMPLETED

Date of Completion: 04/01/2019

Operator Comment: The stormwater BMPs have been fixed around location

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Operator has not provided any documentation attached with this FIRR to indicate or show corrective action has been addressed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed:

Title: EHS Specialist

Date: 4/4/2019 2:15:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401996707	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files