

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401819



PHOTO 1: THE RISERS WERE MARKED.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401819



PHOTO 2: THE RISERS WERE LOTO AND MARKED.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401819



PHOTO 3: THE PC DRIVE AND HYD SKID WERE REMOVED FROM THE LOCATION.

APACHE CANYON 24-02V API# 05-071-07186 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: APRIL 27, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401819



PHOTO 4: THE CEMENT BLOCKS WERE USED TO PROTECT THE WELL HEAD FROM TRAFFIC. THE BLOCKS WERE PLACED BACK AROUND THE WELL HEAD.