

GOLDEN EAGLE 20-05X API# 05-071-08637 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 07, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401823



PHOTO 1: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM THE LOCATION.
(PHOTO TAKEN DURING RAIN SHOWERS).

GOLDEN EAGLE 20-05X API# 05-071-08637 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: MAY 07, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 688401823



PHOTO 2: THE IMPACTED SOIL AROUND THE ENGINE SKID WAS REMOVED FROM THE LOCATION.
(PHOTO TAKEN DURING RAIN SHOWERS).