

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402024538

Date Received:

04/29/2019

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Harkins, Liz</u>	<u>(719) 429-4513</u>	<u>LHarkins@austineexploration.com</u>
<u>Del Hierro, Chris</u>	<u>720-431-7468</u>	<u>chris@CDHconsult.com</u>
<u>Goss, Aaron</u>	<u>303-495-0327</u>	<u>agoss@fremontpetroleum.com</u>
<u>Hart, Tim</u>		<u>thart@fremontpetroleum.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689900575

Inspection Date: 04/09/2019

FIR Submit Date: 04/17/2019

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

### LOCATION - Location ID: 429093

Location Name: Pathfinder Number: C 11-12 1 County: FREMONT

Qtrqr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.328790 Longitude: -105.178678

### FACILITY - API Number: 05-043- -00 Facility ID: 429092

Facility Name: Pathfinder Number: 1

Qtrqr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.328790 Longitude: -105.178678

### CORRECTIVE ACTIONS:

1 ☒ CA# 124355

Corrective Action: Remove and properly store unused and unneeded equipment.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: In accordance with Rule 1003.a., debris has been removed and properly stored at a storage facility. All unused and unneeded equipment has been removed and properly stored.

This CA was originally identified in FIR Document 693900042 (with a required completion date of 4/12/19) and was corrected as of 4/12/19 as evidenced by FIRR Document #402007281. Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 124356

Corrective Action: Interim reclamation needs to be conducted during the spring 2019 planting window, and no later than April 30, 2019, as large portions of the well pad do not appear needed for production operations.

Date: 04/30/2019

Response: CA COMPLETED

Date of Completion: 04/29/2019

Operator Comment: Per 1003 Rules, Operator conducted Interim Reclamation of areas no longer in use. Areas needed for production operations, including equipment operation, access, and oil truck turn around, are clearly delineated. Interim reclamation activities included recontouring and decompacting of unused areas via cross-ripping, topsoil spreading, soil amendment and hydromulching/hydroseeding. Fencing has been installed to prevent driving and/or operations on newly reclaimed areas.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3 ☒ CA# 124357

Corrective Action: Stormwater controls need to be installed within the eastern project area. Any erosion on the well pad cut-slope needs to be stabilized. Install or repair required BMPs per Rule 1002.f.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: In accordance with Rule 1002.f., stormwater controls and BMPs have been installed on the eastern, northwestern and western portions of the pad. Erosion on the cut-slope has been stabilized via erosion control blankets. BMPs consisting of straw wattles, berms, erosion control blankets, grading, and hydromulch/hydroseeding have been installed and/or maintained.

This CA was originally identified in FIR Document 693900042 (with a required completion date of 4/12/19) and was corrected as of 4/12/19 as evidenced by FIRR Document #402007281. Please see attached photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CAs 1 and 3 from this FIR were originally identified in FIR Document 693900042 (with a required completion date of 4/12/19) and were corrected as of 4/12/19 as evidenced by FIRR Document #402007281.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Del Hierro

Signed: \_\_\_\_\_

Title: Agent

Date: 4/29/2019 4:39:46 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402024538	FIR RESOLUTION SUBMITTED
402024569	Erosion blankets
402024576	seeding of Northern slope
402025604	Reclaimed, re-seeded area near pumpjack
402025606	Reclaimed, re-seeded area near flare
402025608	Reclaimed, re-seeded area at south end of pad
402025614	Reclaimed, re-seeded area at north access road

Total Attach: 7 Files