



**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	PHOTO 3-7: ROAD ACROSS STATE WATERS CROSSING EAST OF LOCATION IS ERODING ON NORTH AND SOUTH SIDES OF CROSSING.		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.	Date:	06/10/2019

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS PLUMBED TO SURFACE		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 287977 Type: WELL API Number: 071-09073 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	301100	1941952	
	301100	1941952	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695100641	LOCATION PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4821037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4821037</a>