

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2019

Submitted Date:

05/03/2019

Document Number:

696600033**FIELD INSPECTION FORM**Loc ID 420191 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Clark, Chris		cogccnotifications@laramie-energy.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420190	WELL	PR	09/01/2016	GW	077-10124	Kimball Creek 14-406D-995	PR
420542	WELL	PR	09/01/2016	GW	077-10137	Kimball Creek 11-416D-995	PR

General Comment:[Routine FIU General Field Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Wellhead signs contain previous operators name			
Corrective Action:	Install sign to comply with Rule 210.b		Date:	06/03/2019
Type	TANK LABELS/PLACARDS			
Comment:	Labels faded or missing on Methonal tank. Production tanks contains previous owners name Tank capacity not legible			
Corrective Action:	Install sign to comply with Rule 210.d.		Date:	06/03/2019
Emergency Contact Number:				
Comment:	911 missing from tank battery sign 1-800-891-6191 posted			
Corrective Action:	Install sign to comply with Rule 210.b			Date: 06/03/2019
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Equipment:				
Type: Bird Protectors	# 2			corrective date
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:				

Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected FacilitiesFacility ID: 420190 Type: WELL API Number: 077-10124 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing Well](#)

Corrective Action:

Date:

Facility ID: 420542 Type: WELL API Number: 077-10137 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing Well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Waddles	Pass					
Slope Roughening	Fail					
		Culverts	Pass			
Drains	Pass					
		Ditches	Pass			
		Compaction	Pass			
Compaction	Pass					
		Gravel	Pass			
Berms	Pass					

Comment: Erosion is evident along unstabilized slope on the west side of location .

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/03/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 05/02/2019 at approximately 1438 hours, I, Inspector Dougo Wentzel, conducted a field inspection at the Laramie Energy, Kimbal Creek #14-406D-995, API # 077-10121, in MesaCounty, Colorado.</p> <p>While there, I observed only a Production Operation happening on location.</p> <p>During this inspection some compliance issues were observed.</p> <p>Sign and labels need replaced, repaired and updated with only curent operator. see photo log</p> <p>Stormwater erosion on west slope not being managed at time of inspection. See photo log 911 not posted on battery sign</p>	wentzeld	05/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402032639	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815355
696600034	Inspection 696600033 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4815341