

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/14/2019

Submitted Date:

05/14/2019

Document Number:

685100942**FIELD INSPECTION FORM**Loc ID 320339 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments8 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	left msg 9/21
Canfield, Chris		chris.canfield@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203490	WELL	PR	12/01/2017	OW	001-09050	BADGER OIL 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil in front of crude oil tanks		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	OTHER		
Comment:	Stained soil under load out line for crude oil tanks		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused flow back tank by wellhead stained soil		
Corrective Action:	Comply with Rule 603.f .	Date:	10/22/2017
Type	OTHER		
Comment:	Stained soil around wellhead		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	11/05/2018
Type	TRASH		
Comment:	Trash and unused buckets in separator house		
Corrective Action:	Comply with Rule 603.f .	Date:	10/19/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Barbwire/hog fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		

Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas powered motor	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	PBV FIBERGLASS		39.983610,-103.728250
Comment:	Placard faded and not visible. Sign not legible				
Corrective Action:	Install sign to comply with Rule 210.e.				Date: 11/05/2018

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		39.983830,-103.728190
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Inspected Facilities									
Facility ID:	203490	Type:	WELL	API Number:	001-09050	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: 101979Lat: 39.983607Long: -103.727921

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment: Berms in disrepair, berms do not have 2' of free board

Corrective Action

Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.Date: 10/26/2018**Fencing:**

Fencing Type:

Fencing Condition:

Comment: Hog Fence

Corrective Action

Date: _____

Netting:

Netting Type:

Netting Condition:

Comment: No netting installed over pits on location.

Corrective Action

Net or fence pit to prevent access per rule 902.d.Date: 05/20/2019

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/7/19 at approximately 1000 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resources INC Badger Oil 1 001-09050 in Adams County Colorado.</p> <p>While there, I observed Producing Well</p> <p>This is a follow up inspection from document # 688400360 & 685503909</p> <p>Corrective Actions from previous inspections are delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil under load out line for crude oil tanks</p> <p>Properly treat or dispose of oily waste in accordance with 907.e 11/5/18</p> <p>Trash and unused buckets in separator house</p> <p>Comply with Rule 603.f . 10/19/18</p> <p>Unused flow back tank by wellhead stained soil</p> <p>Comply with Rule 603.f . 10/22/17</p> <p>Stained soil around wellhead</p> <p>Properly treat or dispose of oily waste in accordance with 907.e 11/5/18</p> <p>Stained soil in front of crude oil tanks</p> <p>Properly treat or dispose of oily waste in accordance with 907.e 11/5/18</p> <p>Placard faded and not visible. Sign not legible</p> <p>Install sign to comply with Rule 210.e. 11/5/18</p> <p>Berms in disrepair, berms do not have 2' of free board</p> <p>Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. 10/26/18</p> <p>No netting installed over pits on location.</p> <p>Net or fence pit to prevent access per rule 902.d. 5/20/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	05/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100943	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4822474