

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/16/2019

Submitted Date:

05/16/2019

Document Number:

685100948

FIELD INSPECTION FORM
 Loc ID 318072 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 70385

Name of Operator: SMITH ENERGY CORP

Address: 12706 SHILOH RD

City: GREELEY State: CO Zip: 80631

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
Gillette, Kira		kira.gillette@state.co.us	
Smith, Glen		smithenergy@live.com	
Benish, Erick	(970) 630-5723	Entrulc@gmail.com	
Gomez, Jason		jason.gomez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240554	WELL	SI	09/01/2018	OW	123-08342	CUYKENDALL 12	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Remove weeds around sep, tnk btry, and wh. Remove trash and unused oil containers inside pumping unit house. stained soil in various areas on location. buckets and yellow lid around location. see pic 2,3,4,5,6,7,8,9,10		
Corrective Action:	Remove debris per Statewide equipment, weeds, waste, and trash requirements according to rule 603 f.	Date:	10/16/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	4' barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	4' barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	4' barb wire		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 2		corrective date
Comment:			
Corrective Action:		Date:	
Type: VRU	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	stained soil, possible leak see pic 7		

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	06/16/2019	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		40.128880,-104.392670
Comment:	No capacity sign on oil tank. Thief hatch appears to be open to atmosphere.				
Corrective Action:	Install sign to comply with Rule 210.b.				Date: 06/16/2019

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	PBV FIBERGLASS		40.128880,-104.392670	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with oil tank.				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240554	Type:	WELL	API Number:	123-08342	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/16/19 at approximately 1100 I, Inspector Justin Medina conducted an on-site inspection at Cuykendall 12 Smith Energy Corp 123-08342 in Weld County Colorado. While there, I observed Shut in well</p> <p>This is a follow up inspection from document # 688400338</p> <p>Corrective Actions from previous inspection appear to be delinquent.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Remove weeds around sep, tnk btry, and wh. Remove trash and unused oil containers inside pumping unit house. stained soil in various areas on location. buckets and yellow lid around location. see pic 2,3,4,5,6,7,8,9,10</p> <p>Remove debris per Statewide equipment, weeds, waste, and trash requirements according to rule 603 f. 10/16/18</p> <p>stained soil, possible leak see pic 7</p> <p>Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 6/16/19</p> <p>No capacity sign on oil tank. Thief hatch appears to be open to atmosphere.</p> <p>Install sign to comply with Rule 210.b. 6/16/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection</p>	medinaj	05/16/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685100949	loc pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4825735