

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

06/03/2019

Document Number:

689900773**FIELD INSPECTION FORM**
 Loc ID 307317 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 21603 HIGHWAY 12City: TRINIDAD State: CO Zip: 81082**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ediefitzgerald@tcenergy.us	
		robfoos@tcenergyllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217446	WELL	PR	10/01/1996	GW	071-06223	APACHE CANYON 20-1	RI

**General Comment:**

This is a Stormwater inspection.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The main road in The Southfork has areas of road damage (potholes) causing vehicles to widen the road. The road needs to be graded and maintained. There is erosion occurring off the northeast side of the pad. Sediment is accumulating near the culvert of the access road. See Attached Photos

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 07/01/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689900774	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838677">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4838677</a>