

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2019

Submitted Date:

06/04/2019

Document Number:

688304503**FIELD INSPECTION FORM**Loc ID 316992 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Warner, Ross	720-309-9380	ross.magpieoil@gmail.com	All Inspections
Quint, Craig		craig.quint@state.co.us	
Koehler, Bob		bob.koehler@state.co.us	
Warner, Ryan and James	(970) 669-6308	magpieoil@yahoo.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234150	WELL	SI	06/01/2018	GW	121-06251	LITTLE BEAVER UNIT 30	SI

General Comment:[UIT MIT Pretest, failed per operator](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	steel panels in dryland crop field		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	#		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:		Date:			

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 234150 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ **Date:** _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Inspected FacilitiesFacility ID: 234150 Type: WELL API Number: 121-06251 Status: SI Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/25/2014

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: Per operator, pretest failed. Per Bob Koehler's email to operator on 6/3/2019, "The wells must be repaired and pass an MIT before being returned to service or be plugged and abandoned by 12/3/2019. Both wells must also remain Shut In until they pass an MIT or are plugged and abandoned."

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: 06/18/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688304769	Magpie Operating Little Beaver Unit 30 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4839412
688304770	Magpie Operating Little Beaver Unit 30 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4839413