

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2019

Submitted Date:

06/04/2019

Document Number:

693500277**FIELD INSPECTION FORM**
 Loc ID 317867 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240089	WELL	PR	03/01/2018	GW	123-07877	GREELEY NATIONAL BANK B 3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign no legible		
Corrective Action:	Comply with rule 210e	Date:	06/02/2019

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240089 Type: WELL API Number: 123-07877 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday June 4, 2019 at approximately 0953hrs, I Randy Silver, conducted an on-site inspection at a KP Kauffman site Greely National Bank B#3, at API # 05-12-07877 in Weld County Colorado.</p> <p>While there, I observed a Well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign not legible: Rule 210e Corrective action date of 6-2-19</p> <p>This is a follow up inspection per doc#688402091 at time of inspection Corrective action had not been addressed.</p> <p>Weather conditions: Clear and sunny location and road are muddy inspo.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	06/04/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402064401	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4840013
693500278	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4839981