

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402084128

Date Received:

06/21/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10548

Name of Operator: HRM RESOURCES II LLC

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Ferrin, Jeremy

jeremy.ferrin@state.co.us

Pape, Terry

tpape@hrmres.com

richard_cottle@pogresources.com

dnr_cogccenforcement@state.co.us

lrhutson@hrmres.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682504828

Inspection Date: 04/25/2019

FIR Submit Date: 05/01/2019

FIR Status: _____

Inspected Operator Information:

Company Name: HRM RESOURCES II LLC

Company Number: 10548

Address: 410 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 313925

Location Name: ALISSA-66N60W Number: 5NWSE County: MORGAN

Qtrqr: NWSE Sec: 5 Twp: 6N Range: 60W Meridian: 6

Latitude: 40.515350 Longitude: -104.115975

FACILITY - API Number: 05-087- -00 Facility ID: 227270

Facility Name: ALISSA Number: 1

Qtrqr: NWSE Sec: 5 Twp: 6N Range: 60W Meridian: 6

Latitude: 40.515350 Longitude: -104.115975

CORRECTIVE ACTIONS:

1 CA# 124778

Corrective Action:

Date: 11/15/2016

Perform reclamation in accordance to COGCC 1000 series reclamation rules. Perform compaction alleviation, re-grade/re-contour access road to that of the adjacent reference areas. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture that matches the adjacent pastureland or a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 11/15/2016

Response: CA COMPLETED

Date of Completion: 06/19/2019

Operator Comment: The former access road was deep ripped to alleviate compaction and reseeded using a dry prairie seed mix on June 19, 2019. Bare areas on the former well pad were also ripped and reseeded. The remaining portions of the former well pad, and some area outside the fence adjacent to the former well pad with reduced growth, were overseeded.

COGCC Decision:

COGCC Representative:

2 CA# 124779

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/25/2019

Response: CA COMPLETED

Date of Completion: 05/23/2019

Operator Comment: Repair of the erosion control structures was performed on May 23, 2019. See the attached report.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David K Nicholson

Signed:

Title: Consultant to HRM

Date: 6/21/2019 2:37:30 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files