

GM 44-1

05-045-07448



Separators battery sign.



Well heads.

GM 44-1
05-045-07448



Ditch has been cleaned out and rip rap added.



Ditch has been cleaned out and rip rap added.

GM 44-1
05-045-07448



Washed out berm has been repaired.



Washed out berm has been repaired.

GM 44-1
05-045-07448



Check dam has been maintained.



Culvert outlet basin maintained.

**GM 44-1
05-045-07448**



Erosion damage from culvert has not been repaired.



Sediment build up in road ditch along entrance access road.