

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401765610

Date Received:

09/21/2018

FIR RESOLUTION FORM

CA Summary:

7 of 7 CAs from the FIR responded to on this Form

7 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 88380  
Name of Operator: TINDALL OPERATING COMPANY  
Address: P.O. BOX 4507  
City: ENGLEWOOD State: CO Zip: 80155

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Charles Davis	303-825-8956	dnroilgas@hotmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691200350  
Inspection Date: 08/20/2018 FIR Submit Date: 08/21/2018 FIR Status:

Inspected Operator Information:

Company Name: TINDALL OPERATING COMPANY Company Number: 88380  
Address: 12741 E CALEY STE 142  
City: CENTENNIAL State: CO Zip: 80111

LOCATION - Location ID: 326976

Location Name: NICKERSON-67N58W Number: 18SWNW County:  
Qtrqr: SWN Sec: 18 Twp: 7N Range: 58W Meridian: 6  
W  
Latitude: 40.576536 Longitude: -103.914166

FACILITY - API Number: 05-123-00 Facility ID: 326976

Facility Name: NICKERSON-67N58W Number: 18SWNW  
Qtrqr: SWN Sec: 18 Twp: 7N Range: 58W Meridian: 6  
W  
Latitude: 40.576536 Longitude: -103.914166

CORRECTIVE ACTIIONS:

1 CA# 118013

Corrective Action: Comply with Rule 605.d. Date: 09/20/2018

Response: CA COMPLETED Date of Completion: 09/17/2018

Operator Comment: Work completed by Todd Troutman of DC Dozier - shoveled outside, added clean gravel around engine base, engine house. Removed stained soil and disposed at North Weld Landfill. All pipes, valves, etc. checked and tightened

COGCC Decision: Not Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms stained soil remains around engine base. Corrective Action has NOT been addressed. Refer to comment / photos from that document. Charles Davis with DNR Oil & Gas and Tindall Operating responded by voicemail on 06/28/2019 indicating plans to remove all equipment and commence plugging & remediation operations when wheat crop is harvested by the end of summer 2019.

2  CA# 118014

Corrective Action:  Date: 09/20/2018

Response: CA COMPLETED Date of Completion: 09/19/2018

Operator Comment:

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms chemical containers placarding/labeling has been applied but appears to be fading. Corrective Action appears addressed.

3  CA# 118016

Corrective Action:  Date: 08/28/2018

Response: CA COMPLETED Date of Completion: 09/17/2018

Operator Comment:

COGCC Decision: **Not Approved**

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms gaps remain under produced H2O pit netting. Corrective Action has NOT been addressed. Refer to comment / photos from that document.

4  CA# 118050

Corrective Action:  Date: 10/22/2018

Response: CA COMPLETED Date of Completion: 09/07/2018

Operator Comment:

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms New posted Emergency number appears to be valid. Well is in close proximity to battery. Battery signage contact number is adequate for well. Corrective Action appears addressed.

5  CA# 118051

Corrective Action:  Date: 09/20/2018

Response: CA COMPLETED Date of Completion: 09/20/2018

Operator Comment:

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms Wildlife protection screen NOW observed on heated separator stack. Corrective Action appears addressed.

6  CA# 118052

Corrective Action:  Date: 10/22/2018

Response: CA COMPLETED

Date of Completion: 09/07/2018

Operator Comment: contact numbers posted

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms New posted Emergency number appears to be valid. Well is in close proximity to battery. Battery signage contact number is adequate for well. Corrective Action appears addressed.

7  CA# 118053

Corrective Action: Comply with Rule 210.b.

Date: 04/08/2017

Response: CA COMPLETED

Date of Completion: 09/08/2018

Operator Comment: contact numbers posted

COGCC Decision: Approved

COGCC Representative: Follow-up Field Inspection Report Doc #696100968 dated 05/30/2019 confirms New posted Emergency number appears to be valid. Well is in close proximity to battery. Battery signage contact number is adequate for well. Corrective Action appears addressed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Carrie Witzel

Signed:

Title: Vice President

Date: 9/21/2018 8:47:38 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401765610	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files