

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2019

Submitted Date:

07/11/2019

Document Number:

687905145**FIELD INSPECTION FORM**
 Loc ID 333710 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	970-563-4000	maralextech@gmail.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265538	WELL	PR	10/15/2003	GW	067-08770	JENNIE ROSE 33-7-3 1	PR

General Comment:

This is a follow up inspection from previous inspection doc#687904758. This inspection does not allieviate corrective actions from prior inspections performed. Any completed corrective actions will be noted in this report. Photos are at the end of this inspection report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Parts laying on 55 gallon drum have been removed. Sucker rod and timbers laying along side of pumpjack currently still there.		
Corrective Action:	Comply with Rule 603.f.	Date:	06/16/2019
Type	WEEDS		
Comment:	Weeds and vegetation around separator, meter house need to be controlled.		
Corrective Action:	Comply with Rule 603.f.	Date:	05/26/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Engine oil with staining of gravel/soil below engine. Repair leaking equipment and remediate soil and gravel and dispose of in accordance with regulations. Soil/gravel was removed from underneath pumpjack engine, but not disposed of properly and is now spread along the northern side of pumpjack on ground.		
Corrective Action:	Comply with Rule 1002.f.(2)	Date:	07/16/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	265538	Type:	WELL	API Number:	067-08770	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for 55 gal drum

Comment: 55 gallon drum sitting at separator, with vacuum breaker hose into barrel has spill prevention in place.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905146	Weeds.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876076
687905147	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876077
687905148	Oily gravel/soil removed from under engine.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876078
687905149	Oily gravel/soil not disposed properly.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876079
687905150	Oily gravel/soil not disposed properly.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876080
687905151	Spill prevention on 55 gal drum.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4876081