

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2019

Submitted Date:

07/15/2019

Document Number:

687905155

FIELD INSPECTION FORM

Loc ID 325672 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES, L.L.C.
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Callahan, Linda	(918) 712-8828	lcallahan3@swbell.net	e-mail receipient
Labowskie, Steve		steve.labowskie@state.co.us	
Stevens, Glenn	(970) 749-0192	glennstevens@centurylink.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215209	WELL	PR	05/28/2003	OW	067-06814	PAYNE-SCHMITT 1	PR

General Comment:

[Site inspection with photos at the end of this report.](#)

Location						
Lease Road:						
Type	Access					
comment:	Two-track dirt road on private property.					
Corrective Action					Date:	
Overall Good: <input type="checkbox"/>						
Signs/Marker:						
Type	WELLHEAD					
Comment:	Sign posted at wellhead.					
Corrective Action:					Date:	
Type	TANK LABELS/PLACARDS					
Comment:	Tank labels/placards are fading and starting to come off storage tanks.					
Corrective Action:					Date:	
Emergency Contact Number:						
Comment:	Contact information and 911 posted on sign.					
Corrective Action:					Date:	_____
Good Housekeeping:						
Type	WEEDS					
Comment:	Weeds around pump jack.					
Corrective Action:	Control weeds around equipment per Rule 603.f.				Date:	07/25/2019
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
Equipment:						
Type: Prime Mover	# 1				corrective date	
Comment:	Prime mover has engine oil leak staining soil below it.					
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.				Date:	08/15/2019
Type: Ancillary equipment	# 1					
Comment:	Wellhead.					
Corrective Action:					Date:	
Type: Flow Line	# 2					
Comment:	1-2" flowline from wellhead to oil tanks. 1-1" flowline from wellhead to pumpjack engine fuel gas.					
Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	

CRUDE OIL	2	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 215209 Type: WELL API Number: 067-06814 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
				Material Handling And Spill Prevention	Fail	
Compaction	Pass	Compaction	Pass			

Comment: Spill prevention for 55 gallon drums is inadequate because the drain plug in the bottom is missing. It will not hold liquid in the event of a spill.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 08/15/2019

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905169	Spill prevention missing plug.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879072
687905170	Weeds around equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879073
687905171	Engine oil leak.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4879074