

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/10/2019

Submitted Date:

07/11/2019

Document Number:

696200372**FIELD INSPECTION FORM**

Loc ID 313671 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 4040 BROADWAY STREET #510City: SAN ANTONIO State: TX Zip: 78209**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		dkunovic@passcreekresource.com	
		gwehrer@passcreekresource.com	
		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224819	WELL	PR	10/01/2018	GW	087-05206	NICHOLS 3	RI

General Comment:

This is a follow-up good housekeeping inspection.

This inspection is to document compliance for the following corrective actions:

210.b: Install sign to comply with Rule 210.b

603.f: Comply with Rule 603.f (Weeds).

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign at wellhead has been updated with correct information in accordance with 210.b. This corrective action has been addressed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Previous inspection documented noxious weeds (Canada thistle, <i>Cirsium arvense</i>) on the location and required operator to conduct weed management.</p> <p>Sufficient and ongoing weed management does not appear to be occurring; Canada thistle remains evident at well and location. Additionally Musk thistle (<i>Carduus nutans</i>) is evident on the location. Weedy vegetative growth has established/accumulated around the well and production equipment; This is considered a fire hazard and needs to be removed.</p> <p>Original corrective action has not been addressed and remains applicable.</p>		
Corrective Action:	Comply with Rule 603.f. Ongoing weed management and monitoring is required, and needs to occur in accordance to COGCC rules and regulations.	Date:	05/25/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 224819 Type: WELL API Number: 087-05206 Status: PR Insp. Status: RI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402105536	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875921
696200373	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4875910