

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402106041

Date Received:

07/14/2019

FIR RESOLUTION FORM

CA Summary:

5 of 9 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 83130

Name of Operator: STRACHAN EXPLORATION INC

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Stephen M Strachan

Phone

303-790-9115

Email

sms@strachanexploration.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689900683

Inspection Date: 05/15/2019

FIR Submit Date: 05/16/2019

FIR Status: _____

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 383 INVERNESS PKWY, STE 360

City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 324831

Location Name: FRAZEE-619S50W Number: 6NWNW County: KIOWA

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6
W

Latitude: 38.438830 Longitude: -103.060030

FACILITY - API Number: 05-061- -00 Facility ID: 213004

Facility Name: FRAZEE Number: 2-6

Qtrqr: NWN Sec: 6 Twp: 19S Range: 50W Meridian: 6
W

Latitude: 38.438830 Longitude: -103.060030

CORRECTIVE ACTIONS:

3 ☒ CA# 125238

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 07/14/2019

Operator
Comment:

We are in receipt of the inspection 5/16/19, Thursday evening, with a compliance date of Monday 5/20/19. With this being Friday afternoon, and a compliance date of Monday, we do not have the time or the opportunity to hire contractors to test, sort, build a containment location, if necessary, and dispose of unknown liquids with the submitted time frame. For localized instances, such as these, a 30-day time frame is more appropriate to be able

to identify, evaluate, determine materials and arrange for disposal.

On 5/18, 5/20, 5/29, and 7/3, all barrels and 3 production tanks were emptied by vac truck and fluid disposed of (see attached tickets 30802, 30806, 30829, 34122).

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 125239

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.

Date: 05/20/2019

Response: CA COMPLETED

Date of Completion: 07/14/2019

Operator Comment: We are in receipt of the inspection 5/16/19, Thursday evening, with a compliance date set at 5/20/19, Monday. With today being Friday, we do not have the time available to hire contractors, testers and arrange for disposal by Monday 5/20/19. we believe the stained soils around the wellhead, pumpjack and shed are localized spotting that can be cleaned and resolved within a 30-day window. If testing of soils or other waste is required, we would need 30 days to contract for testing and disposal. Attempting a cleanup over a weekend is not possible without adequate contractor lead time.

On 5/18, 5/20, 5/29, and 7/3, all barrels and 3 production tanks were emptied by vac truck and fluid disposed of (see attached tickets 30802, 30806, 30829, 34122).

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 ☒ CA# 125240

Corrective Action: Comply with Rule 603.f .
Remove all unused equipment and debris.

Date: 08/15/2019

Response: CA COMPLETED

Date of Completion: 07/15/2019

Operator Comment: From 6/24 through 7/9, a total of 128,140 lbs of steel (64 tons) was recycled in Lamar (please see attached tickets #8595-8676).

COGCC Decision: Approved pending re-inspection

COGCC Representative: By the photos it appears to be all cleaned up.

8 ☒ CA# 125243

Corrective Action: Install sign to comply with Rule 210.d.

Date: 06/15/2019

Response: CA COMPLETED

Date of Completion: 07/14/2019

Operator Comment: Sign installed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

9 ☒ CA# 125244

Corrective Action:

Date: _____

Prevent vehicle disturbance outside of the access road and reclaim disturbance.
Properly grade and install road base to allow stormwater drainage.
Properly store and prevent spills.
Install or repair required BMPs per Rule 1002.f.

Response: CA COMPLETED

Date of Completion: 07/14/2019

Operator Comment: The Field access road was regraded, ditches cut and road was topped with gravel. Off road access has been limited with new ditches.

COGCC Decision: Approved pending re-inspection

COGCC Representative: By the photos it appears the road has repaired.

OPERATOR COMMENT AND SUBMITTAL

Comment: Weather and rains have slowed the clean up and road work, but now the road is improved, unused equipment has been scrapped, oily dirt has been collected, stored and analyzed and accepted for disposal at the Otero County Landfill (see attached Manifest), oil field waste disposal tickets and scrapped metal tickets attached, photos of road work and cleaned up storage yard photos attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Stephen M Strachan

Signed: _____

Title: President

Date: 7/14/2019 6:24:19 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402106041	FIR RESOLUTION SUBMITTED
402107707	Haswell Storage Yard Post Cleanup
402107708	Haswell Field Lease Road Post Repairs
402107713	Scrap Metal Disposal Tickets
402107716	Oily Waste Analysis Invoice and Disposal Tickets

Total Attach: 5 Files