

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

685101426**FIELD INSPECTION FORM**

Loc ID 320225 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:

**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments10 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	<a href="#">left msg 9/21</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	SI

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	ROAD INTO LOCATION NEEDS TO BE REBUILT		
Corrective Action	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.	Date:	10/06/2017
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/01/2018
Type	TANK LABELS/PLACARDS		
Comment:	No placard/contents/capacity on tank. see pics		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	No cap on load line of production tanks		
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.	Date:	10/11/2018
Type	WEEDS		
Comment:	Weeds throughout location and road		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused 2" pipe by well head and pit		
Corrective Action:	Comply with Rule 603.f .	Date:	11/01/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PIT		
Comment:	FENCE NEEDS REPAIRED AROUND PIT		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	09/21/2017
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 1	corrective date	
Comment: _____			

Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	No plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 0		
Comment:	No bird protector on separator		
Corrective Action:	Install or repair wildlife protection equipment Comply with rule 324 A.a		Date: 05/20/2019
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
	1				39.955090,-103.935000
Comment:	no content/placard/capacity				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank(s)			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date: 10/06/2017

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	203117	Type:	WELL	API Number:	001-08525	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: _____	Other: _____	Length: _____	Width: _____	

**Lining:**

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

**Fencing:**Fencing Type: Netting/Fence.comFencing Condition: Inadequate

Comment:

Corrective Action

Date: 09/21/2017**Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 5/13/19 at approximately 1000 I, Inspector Justin Medina conducted an onsite inspection at Fritzler Resources INC Linnebur 24-1 001-08525 in Adams County Colorado.</p> <p>While there, I observed Shut in well</p> <p>This is a follow up inspection from document # 685503722 &amp; 88400352 &amp; 685100935</p> <p>All CA are delinquent as of 10/6/17</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>ROAD INTO LOCATION NEEDS TO BE REBUILT</p> <p>Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. 10/6/17</p> <p>Sign not posted or information inaccurate at well(s) or battery</p> <p>Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S. 11/1/18</p> <p>NO PLACARDING ON PROD TANK</p> <p>Install sign to comply with Rule 210.d. 10/6/17</p> <p>Unused 2" pipe by well head and pit</p> <p>Comply with Rule 603.f . 11/1/18</p> <p>No cap on load line of production tanks</p> <p>Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O. 10/11/18</p> <p>CONTROL WEEDS ON LOCATION AND ROAD WAY</p> <p>Comply with Rule 603.f . 10/18/18</p> <p>FENCE NEEDS REPAIRED AROUND PIT</p> <p>Location is within a designated setback location, install fencing per Rule 604.c.(2)M. 9/21/17</p> <p>Inadequate berms around tank(s)</p> <p>Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. 10/6/17</p> <p>No Bird protector on separator</p> <p>Net or fence pit to prevent access per rule 902.d. 5/20/19</p> <p>Barbwire. Fence around pit in disrepair.</p> <p>Location is within a designated setback location, install fencing per Rule 604.c.(2)M. 9/21/17</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101427	Pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889821">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889821</a>