

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

685101429**FIELD INSPECTION FORM**Loc ID 319940 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments6 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fritzler, Gene	970-768-0845	gfritzler@bresnan.net	<a href="#">left msg 9/21</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201955	WELL	PR	09/19/2007	OW	001-07359	SIMPSON A 9	PR

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank has no labels/faded		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/04/2018

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Stained soil around crude oil tanks		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	11/01/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location, PU, meter house, 3 vertical separators, sucker rods next to separator fiberglass pipe on berm of pit		
Corrective Action:	Comply with 603 f.	Date:	01/01/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Tank	>= 5 bbls	
Comment:	possible spill from what appears to be leaking bottom of tank see pic 14		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 07/26/2019

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	#		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric box		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	shares containment with oil tank, no produced water sign on tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate



Inspected Facilities									
Facility ID:	201955	Type:	WELL	API Number:	001-07359	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Fail	

Comment: [multiple buckets and drums on location with unknown contents](#)

Corrective Action: [Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.](#)

Date: 07/26/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: Other: Length: Width:

**Lining:**

Liner Type: Liner Condition:

Comment: [What appears to be hydrocarbons in produced water pit see pic 17](#)

Corrective Action

[For non emergencies, remove produced liquid hydrocarbons from the earthen pit or reservoir immediately per Rule 323.. For emergencies, remove produced liquid hydrocarbons from the earthen pit or reservoir immediately after the emergency is over per Rule 323.](#)

Date: 07/25/2019

**Fencing:**

Fencing Type: None Fencing Condition:

Comment: [no fencing](#)

Corrective Action

Date:

**Netting:**

Netting Type: Netting Condition:

Comment: [no netting on pit](#)

Corrective Action

Date:

Anchor Trench Present: NO Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 7/24/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at Fritzler Resouces- API 001-07359 Simpson A9 in Adams County Colorado. While there, I observed Producing Well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Corrective actions are delinquent from previous inspection document # 688400344</p> <p>Produced water tank has no labels/faded</p> <p>Install sign to comply with Rule 210.d. 12/4/2018</p> <p>Stained soil around crude oil tanks</p> <p>Properly treat or dispose of oily waste in accordance with 907.e. 11/1/18</p> <p>Unused equipment on location, PU, meter house, 3 vertical seperators, sucker rods next to separator fiberglass pipe on berm of pit</p> <p>Comply with 603 f.1/1/19</p> <p>possible spill from what appears to be leaking bottom of tank see pic 14</p> <p>Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. 7/26/19</p> <p>multiple buckets and drums on location with unknown contents</p> <p>Non E&amp;P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff. 7/26/19</p> <p>What appears to be hydrocarbons in produced water pit see pic 17</p> <p>For non emergencies, remove produced liquid hydrocarbons from the earthen pit or reservoir immediately per Rule 323.. For emergencies, remove produced liquid hydrocarbons from the earthen pit or reservoir immediately after the emergency is over per Rule 323. 7/25/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	07/24/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685101430	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889822</a>