

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2019

Submitted Date:

07/24/2019

Document Number:

695101120

FIELD INSPECTION FORM

Loc ID 308880 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284264	WELL	PR	07/12/2007	GW	071-08761	BIG TIMER 32-19	PR

General Comment:

INSPECTION SURVEY DATA SHEET IN ATTACHMENTS SECTION OF THIS INSPECTION HAS BEEN REPLACE WITH CORRECT SURVEY DATA SHEET BY TOM BEARDSLEE 7/25/19 07:50.INSPECTION SURVEY DATA SHEET IN ATTACHMENTS SECTION OF THIS INSPECTION HAS BEEN REPLACE WITH CORRECT SURVEY DATA SHEET BY TOM BEARDSLEE 7/25/19 07:54

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Compressor	# 1		
Comment:	Vacuum pump observed on well without COGCC approval.		
Corrective Action:	IMMEDIATELY STOP PRODUCING WELL ON A VACUUM. DO NOT OPERATOR VACUUM EQUIPMENT (COMPRESSOR) WITHOUT COMPLETE COMPLIANCE WITH RULE 331 AND 802.		Date: <u>07/24/2019</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>284264</u>	Type: <u>WELL</u>	API Number: <u>071-08761</u>	Status: <u>PR</u>
			Insp. Status: <u>PR</u>

Complaint	
Comment:	<p>STEVE LABOWSKIE PERFORMED A SOUND STUDY STARTING @ APPROXIMATELY 08:45 A.M. FOR 15 MINUTES. WIND SPEED APP. 1-2 MPH. TEMP 63*</p> <p>SOUND METER SET @ 100' FROM COMPRESSOR EXHAUST. results are 54.4 AVERAGE db (a) calc. to 43.5 db (a) @ 350'.</p> <p>STEVE LABOWSKIE PERFORMED A SOUND STUDY at complainants residence 17775 county road 51.0 STARTING @ APPROXIMATELY 10:00 A.M. FOR 15 MINUTES. WIND SPEED APP. 1-2 MPH. TEMP 65*</p> <p>SOUND METER SET @ 25' FROM residence.</p>
Corrective Action:	<p>TURN EXHAUST OUTLET ON ENGINE SKID FOR DRIVEHEAD 180* SO IT IS NOT POINTING IN THE DIRECTION OF THE HOME TO THE NORTHWEST OF LOCATION COMPLY WITH RULE 802</p>
	Date: <u>07/25/2019</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402121304	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889781
402121454	SOUND SURVEY DATA SHEET @ LOCATION	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889943
695101121	SOUND SURVEY AT RESIDENCE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889777
695101122	SOUND SURVEY AT RESIDENCE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4889778