

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401912434  
Date Received:  
01/21/2019

## FIR RESOLUTION FORM

### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 6720  
Name of Operator: ROBERT L BAYLESS PRODUCER LLC  
Address: 621 17TH ST STE 2300  
City: DENVER State: CO Zip: 80293  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
<u>Trujillo, Helen</u>		<u>notices@rlbayless.com</u>
<u>Trujillo, Helen</u>		<u>htrujillo@rlbayless.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689801837  
Inspection Date: 10/26/2018 FIR Submit Date: 10/26/2018 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: ROBERT L BAYLESS PRODUCER LLC Company Number: 6720  
Address: 621 17TH ST STE 2300  
City: DENVER State: CO Zip: 80293

### LOCATION - Location ID: 316765

Location Name: EILTS-BRADLEY-66N87W Number: 14NENE County: ROUTT  
Qtrqtr: NENE Sec: 14 Twp: 6N Range: 87W Meridian: 6  
Latitude: 40.482740 Longitude: -107.111020

### FACILITY - API Number: 05-107-00 Facility ID: 232728

Facility Name: EILTS-BRADLEY Number: 1-14  
Qtrqtr: NENE Sec: 14 Twp: 6N Range: 87W Meridian: 6  
Latitude: 40.482740 Longitude: -107.111020

### CORRECTIVE ACTIONS:

1 ☒ CA# 119937

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 11/26/2018

Response: CA COMPLETED Date of Completion: 11/05/2018

TIGHTENED CONNECTIONS, REMOVED STAINED SOIL.

Operator  
Comment:

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 119938

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 11/26/2018

Response: CA COMPLETED

Date of Completion: 11/05/2018

Operator  
Comment:

TIGHTEND FITTINGS, REMOVED STAINED SOIL.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 120003

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/26/2018

Response: CA COMPLETED

Date of Completion: 11/05/2018

Operator  
Comment:

BLUE CHEMICAL BARREL REMOVED.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: SORRY ABOUT LATE RESPONSE. GOING THROUGH MY LIST OF THINGS TO DO AND THOUGHT WE HAD SUBMITTED THIS FIR. WORK COMPLETED NOVEMBER 2018.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: HELEN TRUJILLO

Signed: \_\_\_\_\_

Title: OFFICE MANAGER

Date: 1/21/2019 3:39:02 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401912434	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files