

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402029136
Date Received:
05/01/2019

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergy.us</u>
<u>Mack, Ronald</u>		<u>ronaldmack@tcenergy.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401795
Inspection Date: 04/09/2019 FIR Submit Date: 04/09/2019 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308830

Location Name: GOLDEN EAGLE-633S67W Number: 19SENW County: LAS ANIMAS
Qtrqtr: SENW Sec: 19 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.158920 Longitude: -104.930127

FACILITY - API Number: 05-071- -00 Facility ID: 282949

Facility Name: GOLDEN EAGLE Number: 19-6
Qtrqtr: SENW Sec: 19 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.158920 Longitude: -104.930127

CORRECTIVE ACTIONS:

1 ☒ CA# 124057

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A

Date: 05/09/2019

Response: CA COMPLETED

Date of Completion: 04/22/2019

Operator
Comment:

The stained soil around the well head has been removed from the location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693501123.

2 ☒ CA# 124058

Corrective Action: Comply with rule 603 f

Date: 05/09/2019

Response: CA COMPLETED

Date of Completion: 04/22/2019

Operator Comment: All unused equipment was removed from the location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: ased on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693501123.

3 ☒ CA# 124059

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 05/09/2019

Response: CA COMPLETED

Date of Completion: 04/22/2019

Operator Comment: The erosion of the fill slope was corrected. Run off was re-directed to the rip-rap. The dirt berm surrounding the production pit was dominated. See the attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: ased on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693501123.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 5/1/2019 3:23:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402029136	FIR RESOLUTION SUBMITTED
402029172	Photo Log

Total Attach: 2 Files