

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402029187
Date Received:
05/01/2019

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Santistevan, Vince	719-845-2102/719-680-9705	vincesantistevan@tcenergy.us
Mack, Ronald		ronaldmack@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401821
Inspection Date: 04/11/2019 FIR Submit Date: 04/11/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308930

Location Name: APACHE CANYON-634S68W Number: 24SENE County: LAS ANIMAS
Qtrqtr: SENE Sec: 24 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.071566 Longitude: -104.941302

FACILITY - API Number: 05-071- -00 Facility ID: 285176

Facility Name: APACHE CANYON Number: 24-8
Qtrqtr: SENE Sec: 24 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.071566 Longitude: -104.941302

CORRECTIVE ACTIONS:

1 ☒ CA# 124173

Corrective Action: Complete with rule 603 f Date: 05/11/2019

Response: CA COMPLETED Date of Completion: 04/27/2019

Operator Comment: All unused equipment was removed from the location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693501125.

2 ☒ CA# 124174

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A

Date: 05/11/2019

Response: CA COMPLETED

Date of Completion: 04/27/2019

Operator Comment: The stained soil around the liquid ring compressor and the engine skid has been removed from the location. See attached photo log for details.

COGCC Decision: Approved via an AMI

COGCC Representative: Based on Photos subitted be operator all corrective action have been completed. See inspection Doc# 693501125.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: SR. Environmental Tech.

Date: 5/1/2019 3:31:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402029187	FIR RESOLUTION SUBMITTED
402029202	Photo Log

Total Attach: 2 Files