

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/13/2019

Submitted Date:

08/14/2019

Document Number:

689802977**FIELD INSPECTION FORM**Loc ID 324757 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	

**General Comment:****COGCC Inspection Report 689802977 Summary**

On Tuesday 8/13/2019 at approximately 12:20, I, Inspector Emily Waldron, conducted a field inspection at Sandridge Exploration and Production LLC Mutual 01-17H at 324757 in Jackson County Colorado.

While there, I performed a follow up inspection to vehicle tracking issues observed in inspection document number 689802878. Vehicle tracking corrective actions have not been resolved.

During this inspection the following possible compliance issues were observed:

Tracking pad not adequately maintained to prevent track of material offsite. See photos 1-4. Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F. If material is tracked onto County or public roads, contact the appropriate authority by 5/6/2019.

I spoke with Russel Shipley and Spence Laird of Sandridge on 8/14/2019 to discuss addition of tracking measures and to explain that more measures will be needed to return to compliance.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 689802977.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Tracking pad not adequately maintained to prevent track of material offsite.](#)

Corrective Action: [Maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.\(2\)F. If material is tracked onto County or public roads, contact the appropriate authority.](#)

Date: 05/06/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402144748	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909155">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909155</a>
689802978	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909146">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4909146</a>