

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402162513

Date Received:  
08/30/2019

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed  
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 60890 Contact Name and Telephone:  
Name of Operator: MOUNTAIN PETROLEUM CORP Name: \_\_\_\_\_  
Address: PO BOX 5043 Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
City: BUENA VISTA State: CO Zip: 81211 Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Steve Matre</u>	<u>720-400-3592</u>	<u>mtenergylock@gmail.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901190  
Inspection Date: 08/26/2019 FIR Submit Date: 08/28/2019 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MOUNTAIN PETROLEUM CORP Company Number: 60890  
Address: PO BOX 5043  
City: BUENA VISTA State: CO Zip: 81211

LOCATION - Location ID: 380452

Location Name: SSM UPRR Number: 1-5 County: CHEYENNE  
Qtrqr: SENE Sec: 5 Twp: 15S Range: 48W Meridian: 6  
Latitude: 38.773210 Longitude: -102.797650

FACILITY - API Number: 05-017-00 Facility ID: 207498

Facility Name: SSM UPRR Number: 1-5  
Qtrqr: SENE Sec: 5 Twp: 15S Range: 48W Meridian: 6  
Latitude: 38.773210 Longitude: -102.797650

CORRECTIVE ACTIONS:

1 CA# 129760

Corrective Action: Comply with 1004 Rules  
Remove all equipment, powerline, and cement pads.  
Reclaim the access road and the location. Date: 11/01/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: I have reviewed the attached inspection report and offer the following comments and information for your consideration.  
1. In October, 2011 Mountain Petroleum Corporation ("MPC") re-entered the subject well, tested two zones and

then abandoned those zones, and plugged and abandoned the well on 10/20/2011. No production operations were conducted by MPC and we would have had no need for power or meters. MPC had obtained the related mineral rights via an option farmout agreement with Anadarko in 2011. Murfin Drilling had drilled and abandoned the original well on 1/21/1984.

2. The location photos taken as part of MPC's permit application to re-enter the well in 2011 are attached. Note that the gate and access road, cement pads, shed, and powerlines shown in the photos you took during your 8/26/2019 inspection are also shown in the photos taken for MPC's 2011 permit. These items were clearly in place before MPC conducted any operations on this location. MPC did level and re-seed the area it disturbed after we plugged and abandoned the well.

3. The items noted in your inspection report appear to have been installed or constructed by, or at the direction of, the landowner. Note that the sign on the shed (which does not appear to be used as a meter shed) has the name "GP Minerals" and "Doris Price" on it. We believe GP Minerals is a commercial firm whose business involves municipal and industrial water; Doris Price was the landowner.

In summary, we believe Mountain Petroleum has appropriately restored the surface location impacted by its operations, and we do not have the authority or responsibility to remove the items noted in your inspection report. We ask that you issue a revised inspection report as appropriate. Please advise if you have questions or need additional information. Thank you.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Steve Matre

Signed: \_\_\_\_\_

Title: Agent

Date: 8/30/2019 11:11:45 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

402162557	6/28/2011 Location Photos for reentry permit
-----------	----------------------------------------------

Total Attach: 1 Files