

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402165696

Date Received:

09/06/2019

FIR RESOLUTION FORM

Overall Status: FRQ

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLC

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Kevin Kane

Phone

303-893-2503

Email

kkane@bayswater.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500545

Inspection Date: 08/29/2019

FIR Submit Date: 09/03/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BAYSWATER EXPLORATION & PRODUCTION LLC

Company Number: 10261

Address: 730 17TH ST STE 500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 433862

Location Name: Hirsch Pad Number: 29-C County: _____

Qtrqr: NWNE Sec: 29 Twp: 7N Range: 66W Meridian: 6

Latitude: 40.551739 Longitude: -104.800709

FACILITY - API Number: 05-123-00 Facility ID: 433862

Facility Name: Hirsch Pad Number: 29-C

Qtrqr: NWNE Sec: 29 Twp: 7N Range: 66W Meridian: 6

Latitude: 40.551739 Longitude: -104.800709

CORRECTIVE ACTIONS:

1  CA# 129979

Corrective Action: Comply with Rule 1004. Collaborate with the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production. Corrective action date is being back-dated to when all final reclamation work should have been completed.

Date: 06/27/2019

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: Bayswater completed the battery removal and site reclamation on or around 4/18/2019. Bayswater coordinated with the landowner and tenant farmer at this location. Bayswater provided top soil and contouring to the landowner/tenant farmer's satisfaction. Due to the late timing of this past growing season, the tenant farmer

elected not to plant this past spring. The farmer has communicated plans to cultivate this location next growing season. Bayswater believes that Rule 1004 has been complied with to the extent possible at this time.

COGCC Decision: **Not Approved**

COGCC
Representative:

COGCC
Supervisor:

Operator has provided no documentation regarding any interactions with the surface owner or documentation of any reclamation activities that might have occurred. Therefore, this Factual review is not approved.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kevin Kane

Signed:

Title: Operations Manager

Date: 9/6/2019 7:47:24 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 402165696 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files