

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/12/2019

Submitted Date:

09/13/2019

Document Number:

689901233**FIELD INSPECTION FORM**Loc ID 307280 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 6295 GREENWOOD PLAZA BLVD #100City: GREENWOOD State: CO Zip: 8111-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		robfoos@tcenergyllc.com	
		ronaldmack@tcenergy.us	
		ediefitzgerald@tcenergy.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217354	WELL	PR	01/01/1995	GW	071-06130	APACHE CANYON 14-1	RI

**General Comment:**

This is a stormwater inspection.

This is a follow up of the previous inspection #689900634, 689900953, 689901103.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Some of the culverts along the road appeared to have been cleaned out. There were some culverts that are filled in with sediment. BMP's need to be installed to prevent erosion and culverts need to be maintained. The road was repaired where stormwater flowed accross the road. See Attached Photo

Corrective Action: Install or repair required BMPs per Rule 1002.f.  
Routinely inspect and maintain culverts.

Date: 10/14/2019

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402176481	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937309">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937309</a>
689901234	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937303">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4937303</a>