

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402185971

Date Received:

09/23/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

7208456901

Email

mcugnetti@verdadoil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697500466

Inspection Date: 08/14/2019

FIR Submit Date: 08/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 5950 CEDAR SPRINGS ROAD

City: DALLAS State: TX Zip: 75235

LOCATION - Location ID: 453512

Location Name: HDI KF Number: 01-65-10 County: _____
PAD

Qtrqtr: SESE Sec: 10 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.060105 Longitude: -104.642444

FACILITY - API Number: 05-123- -00 Facility ID: 453512

Facility Name: HDI KF Number: 01-65-10
PAD

Qtrqtr: SESE Sec: 10 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.060105 Longitude: -104.642444

CORRECTIVE ACTIONS:

1 CA# 129418

Corrective Action: Submit the required information no later than August 27, 2019.

Date: 08/27/2019

Response: CA COMPLETED

Date of Completion: 09/05/2019

Operator Comment: Submitted requested information. Late due to lack of current imagery and availability drone to capture realtime image.

COGCC Decision: _____

COGCC
Representative:

2 CA# 129419

Corrective Action: Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 08/14/2019

Response: CA COMPLETED

Date of Completion: 08/27/2019

Operator
Comment:

Weeds removed and topsoil pile recontoured to allow maintenance and perennial seeding on slopes.

COGCC Decision:

COGCC
Representative:

3 CA# 129420

Corrective Action: Comply with Rule 1003.a. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 08/14/2019

Response: CA COMPLETED

Date of Completion: 09/23/2019

Operator
Comment:

All unused equipment removed from location.

COGCC Decision:

COGCC
Representative:

4 CA# 129421

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance, as the location should be in compliance at all times.

Date: 08/14/2019

Response: CA COMPLETED

Date of Completion: 08/27/2019

Operator
Comment:

Pad erosion corrected and Control Measures repaired and added.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: _____

Title: EH&S Manager

Date: 9/23/2019 3:07:40 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files