

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/27/2019

Document Number:

679705613

FIELD INSPECTION FORM

Loc ID 316452 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 100 CHEVRON USA INC
City: RANGELY State: CO Zip: 81648

Findings:

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276314	WELL	SI	06/01/2019	OW	103-10553	BEEZLEY 4X22	SI
417696	WELL	PR	06/01/2019	OW	103-11742	BEEZLEY 5X22	PR
417699	WELL	PR	03/01/2019	OW	103-11743	BEEZLEY 6X22	PR

General Comment:

[COGCC Inspection Report Summary.](#)

On 9-26-2019 at approximately 17:20, inspector Rick Moran, conducted a routine inspection at Chevron wells Beezley 4X22, 5X22, 6X22 in Rio Blanco county.

The following compliance issues were observed:

- 1) Missing "911" on well head signs & 1 sign lying on ground. Photos 3, 4, 5. Complete by 10-26-2019.
- 2) Red fencing lying on ground. Photo 6. Complete by 10-26-2019.
- 3) Chemical pumps leaks. Photos 7 & 8. Complete by 10-26-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705613.

Location

Overall Good:

Signs/Marker:

Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	"911' missing on well head signs. Beezley 4X22 sign lying on ground.	Date:	10/26/2019
Corrective Action:	Install sign to comply with Rule 210.b.		

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Red fencing lying on ground at edge of location.		
Corrective Action:	Comply with Rule 603.f .	Date:	10/26/2019

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Submersible Pump	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Two containers of corrosion inhibitor and 2 containers of asphaltene inhibitor with secondary containment. 2 chemical pumps had or are currently leaking into the secondary containment. The inspector was unable to determine if the pumps are still leaking.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/26/2019
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 276314 Type: WELL API Number: 103-10553 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last recorded production May 2019.

Corrective Action: _____ Date: _____

Facility ID: 417696 Type: WELL API Number: 103-11742 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on subpump.

Corrective Action: _____ Date: _____

Facility ID: 417699 Type: WELL API Number: 103-11743 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on subpump.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass			Material Handling And Spill Prevention	In Process	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679705614	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948993