

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402036795

Date Received:
05/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Mack, Ronald		ronaldmack@tcenergy.us
Santistevan, Vince	719-845-2102/719-680-9705	vincasantistevan@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688401825
Inspection Date: 04/11/2019 FIR Submit Date: 04/11/2019 FIR Status:

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308441

Location Name: GOLDEN EAGLE-633S67W Number: 17SESW County: LAS ANIMAS
Qtrqtr: SESW Sec: 17 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.166560 Longitude: -104.912800

FACILITY - API Number: 05-071-00 Facility ID: 272124

Facility Name: GOLDEN EAGLE Number: 17-14
Qtrqtr: SESW Sec: 17 Twp: 33S Range: 67W Meridian: 6
Latitude: 37.166560 Longitude: -104.912800

CORRECTIVE ACTIONS:

1 CA# 124176

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 04/12/2019

Operator Comment: The well head packings were securely fastened to stop the leak. See attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501468.

2 CA# 124177

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A Date: 05/11/2019

Response: CA COMPLETED Date of Completion: 05/07/2019

Operator Comment: The impacted soil around the well head has been removed from the location. See attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501468.

3 CA# 124178

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Date: 05/11/2019

Response: CA COMPLETED Date of Completion: 05/07/2019

Operator Comment: The impacted soil around the engine skid was removed from location. See attached photo log for details.

COGCC Decision: Approved

COGCC Representative: Based on Photos subitted by operator all corrective action have been completed. See inspection Doc# 693501468.

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: _____

Title: SR. Environmental Tech. Date: 5/8/2019 2:55:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
402036795	FIR RESOLUTION SUBMITTED
402036820	Photo Log

Total Attach: 2 Files