

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402194343

Date Received:

10/01/2019

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

7 of 7 CAs from the FIR responded to on this Form

7 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10661

Name of Operator: BISON OIL & GAS II LLC

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Todd Wolff</u>	<u>720-644-6997</u>	<u>twolff@bisonog.com</u>
<u>Abigail Wenk</u>	<u>720-644-6997</u>	<u>awenk@bisonog.com</u>
<u>Ariana Solis</u>	<u>720-644-6997</u>	<u>asolis@bisonog.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696200612

Inspection Date: 08/20/2019

FIR Submit Date: 08/21/2019

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: BISON OIL & GAS II LLC

Company Number: 10661

Address: 518 17TH STREET #1800

City: DENVER State: CO Zip: 80202

**LOCATION - Location ID: 454166**

Location Name: Hunt 8-60 Number: 6C County: \_\_\_\_\_

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

**FACILITY - API Number: 05-123-00 Facility ID: 454166**

Facility Name: Hunt 8-60 Number: 6C

Qtrqr: Lot 7 Sec: 6 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.687550 Longitude: -104.141661

**CORRECTIVE ACTIONS:**

**1** CA# 129480

Corrective Action: Install signage/labelling to comply with Rule 210.b.

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/21/2019

Operator Comment: Labels detailing tank content, volume, etc were added to tanks within battery. Barrels of material to remain on site have been placed in a secondary containment and contents/volume are labeled. New labels have been ordered for additional signage.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 129481

Corrective Action: Comply with 603.f

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/06/2019

Operator  
Comment:

Weeds have been removed from location.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 129482

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/21/2019

Operator  
Comment:

Bulk of stained soil originally removed 9/9/2019.  
Additional stained soil/gravel was found under equipment on location and was cleaned or removed 9/30/2019.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**4** CA# 129483

Corrective Action: Install required signage/labelling on barrels/containers to comply with Rule 210.b

Date: 09/21/2019

Response: CA COMPLETED

Date of Completion: 09/21/2019

Operator  
Comment:

White barrel observed during inspection has been removed from location.  
Barrels of material to remain on site have been placed in a secondary containment and contents/volume are labeled. New labels have been ordered for additional signage.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**5** CA# 129484

Corrective Action: Comply with 603.f and 1002.f(2).b and place materials into secondary containment, or remove and properly store.

Date: 03/26/2019

Response: CA COMPLETED

Date of Completion: 08/30/2019

Operator  
Comment:

Barrels of material to remain on site have been placed in a secondary containment and contents/volume are labeled.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**6** CA# 129485

Corrective Action: Comply with 1002.c

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 09/21/2019

Operator Comment: Topsoil has been utilized to recontour and seed pad per interim reclamation process.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**7** CA# 129624

Corrective Action: Comply with COGCC Stormwater Rules: Install or repair required BMPs per Rule 1002.f, and in accordance with good engineering practices.

Date: 04/12/2019

Response: CA COMPLETED

Date of Completion: 09/21/2019

Operator Comment: Numerous BMPs were repaired, added, or modified in addition to initiating the interim reclamation process in order to stabilize location and comply with 1002.f  
Ditches have been cleared of sediment, berms repaired  
Sediment trap on north end of pad has been moved to the northeast corner, and expanded. Additional rip rap was utilized for inlet and outlet protection.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ariana Solis

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 10/1/2019 4:04:22 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402195043	FIRR Photo Report
-----------	-------------------

Total Attach: 1 Files