

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2019

Submitted Date:

10/01/2019

Document Number:

693501474

**FIELD INSPECTION FORM**

Loc ID 318056 Inspector Name: Silver, Randy On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>
Gomez, Jason		jason.gomez@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240513	WELL	PR	05/01/2018	OW	123-08301	CLEVELAND 3	TA

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	

Emergency Contact Number:

Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Flowline risers not LO/TO or marked are considered unused equipment		
Corrective Action:	Comply with Rule 603.f .	Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: PU and associated parts, Electrical panel		
Corrective Action:	Comply with Rule 603.f	Date:	

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 240513 Type: WELL API Number: 123-08301 Status: PR Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Production equipment has been removed from well head. Production flow lines are closed at time of inspection. Well is TA. MIT needs to be preformed in 30 days. Contact COGCC engineering.

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday October 1, 2019 at approximately 12:30PM, I, Inspector Randy Silver, conducted an on-site follow up inspection at a KP Kauffman site Cleveland #3, at API# 05-123-08301 in Weld County Colorado.                      While there, I observed producing well site.                      During this follow up inspection per DOC # 693501284 the following possible compliance issues were still observed:                      Unused equipment: Rule 603 f See Photos 1,2,3,4                      Unused equipment Rule 603 f See Photo 1,2,3,4                      Well head sign: Rule 210 b See photo 1,2,3,4                      Emergency contact: Rule 210 b See photos 1,2,3,4                      After an internal review of recent inspections at KPK facilities, COGCC Staff has determined that KPK has repeatedly and consistently failed to comply with certain COGCC rules (categorized in those inspection reports as violations related to "Signs/Marker," "Emergency Contact Number," and/or "Good Housekeeping"). In light of this apparent pattern of violations, violation(s) identified in this inspection report under those categories are being entered for notification and documentation only and are not intended to provide KPK the potential opportunity to resolve the alleged violation(s) without the imposition of penalty, pursuant to Rule 522.c. Therefore, in this inspection report, COGCC Staff has documented violation(s) and identified relevant corrective action(s) required to return to compliance, and pursuant to Rule 522.c., retains discretion to seek penalties for any violation documented in this inspection report.                      Weather conditions: Cloudy and location wet</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	silverr	10/01/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402194496	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4951569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4951569</a>
693501475	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4951567">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4951567</a>