

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402205680

Date Received:
10/10/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kyle Waggoner

4326616647

kyle.waggoner@whiting.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696200533

Inspection Date: 08/02/2019

FIR Submit Date: 08/05/2019

FIR Status: _____

Inspected Operator Information:

Company Name: WHITING OIL & GAS CORPORATION

Company Number: 96155

Address: 1700 BROADWAY STE 2300

City: DENVER State: CO Zip: 80290

LOCATION - Location ID: 435644

Location Name: Razor Number: 11F Pad County: _____

Qtrqr: SENW Sec: 11 Twp: 10N Range: 58W Meridian: 6

Latitude: 40.854011 Longitude: -103.835472

FACILITY - API Number: 05-123-00 Facility ID: 435644

Facility Name: Razor Number: 11F Pad

Qtrqr: SENW Sec: 11 Twp: 10N Range: 58W Meridian: 6

Latitude: 40.854011 Longitude: -103.835472

CORRECTIVE ACTIONS:

1 CA# 128966

Corrective Action: Conduct stabilization activities on pad per 1003.b. Reclaim the stormwater ditch, and associated stormwater BMPs located on the perimeter of the initial disturbance area and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 10/31/2019

Response: CA COMPLETED

Date of Completion: 09/13/2019

The perimeter ditch and associated BMP's have been removed and/or reclaimed, seeded, and mulched.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 128967

Corrective Action: Install stormwater BMPs to 1) mitigate ponding within the pad/production areas, 2) prevent potential industrial pollutant contact and 3) to allow for sediment laden-free stormwater discharge from the location

Date: 08/23/2019

Response: CA COMPLETED

Date of Completion: 08/22/2019

Operator
Comment:

A ditch and berm have been installed leading to a sediment trap surrounding the working surface of the pad.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kyle Waggoner

Signed:

Title: Field Regulatory Manager

Date: 10/10/2019 1:06:12 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files