

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/10/2019

Document Number:

694500143

FIELD INSPECTION FORM

Loc ID 414031 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10619
Name of Operator: INSPIRE OIL & GAS INC
Address: 1400 BROADFIELD BLVD SUITE 600
City: HOUSTON State: TX Zip: 77084

Findings:

- 9 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	
bo ritz		britz@inspireoilandgas.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412127	WELL	PR	10/20/2012	GW	057-06490	Silver Spur Minerals 35-2H	EI

General Comment:

On 10/9/2019 COGCC staff, Kris Neidel inspected the Silver Spur Minerals #35-2H. Weather was windy, dry, clear and 60 degrees. Corrective actions from previous inspections remain. Well was shut in at time of inspection. See below for corrective actions.

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Sign not posted or information inaccurate at entrance off of Hwy 14. phone number and operator number are for previous operator.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/03/2019
Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Note: Produced water tanks signage, labeling, and placarding illegible.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/03/2019

Emergency Contact Number:

Comment:	Emergency Contact number is for Wellstar not Inspire.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	10/04/2019

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	tubing, drillpipe, trash, barrels, valves, fitting stored on location.		
Corrective Action:	Comply with Rule 603.f	Date:	10/13/2017

Overall Good:

Spills:

Type	Area	Volume	
Crude Oil	Tank	<= 1 bbl	
Comment:	stained soil in tank battery		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a.		Date: 09/04/2019

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>		
Other (Content)	<input type="text"/>		
Other (Capacity)	<input type="text"/>		
Other (Type)	<input type="text"/>		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate

Comment:	The tank secondary containment detentions were estimated and appear to be less than 300bbbs.	
Corrective Action:	Repair or install berms or other secondary containment devices per Ruls 605.a.(4). and 906.d.(1). The operator should ensure that the berm capacity is compliant with rule 605.a.(4)	Date: 11/13/2019

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		

Comment:	Berm is not consolidated.	
Corrective Action:	Repair or install berms or other secondary containment devices per Ruls 605.a.(4).	Date: 10/13/2017

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate

Comment:	Berm is not consolidated.	
Corrective Action:	Repair or install berms or other secondary containment devices per Ruls 605.a.(4) and rule 906.d.(1)	Date: 10/13/2017

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 412127 Type: WELL API Number: 057-06490 Status: PR Insp. Status: EI

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402206403	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4960534
402206579		silver spur 35.pdf
402206580	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4960686
694500144	photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4960531