

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

10/24/2019

Document Number:

689901400**FIELD INSPECTION FORM**

Loc ID 307375 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10672
 Name of Operator: TIMBER CREEK OPERATING LLC
 Address: 6295 GREENWOOD PLAZA BLVD #100
 City: GREENWOOD State: CO Zip: 8111-

Findings:

- 4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------|---------|
| | | robfoos@tcenergyllc.com | |
| | | ronaldmack@tcenergy.us | |
| | | ediefitzgerald@tcenergy.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 217562 | WELL | PR | 08/30/2007 | GW | 071-06339 | APACHE CANYON 18-9 | RI |

General Comment:

This is a follow up of the previous inspection #689901101.
 Corrective action was not performed since previous inspection.
 Corrective action must be performed immediately.

Location

| | | | |
|--------------------|--|-------|--|
| Lease Road: | | | |
| Type | | | |
| comment: | | | |
| Corrective ActionL | | Date: | |

Overall Good:

| | | | |
|----------------------|------|-------|--|
| Signs/Marker: | | | |
| Type | | | |
| Comment: | Good | | |
| Corrective Action: | | Date: | |

| | | | |
|----------------------------------|------|-------|-------|
| Emergency Contact Number: | | | |
| Comment: | Good | | |
| Corrective Action: | | Date: | _____ |

| | | | |
|---------------------------|--|-------|--|
| Good Housekeeping: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|--------------------|--|----------|------------------|
| Spills: | | | |
| Type | Area | Volume | |
| Produced Water | WELLHEAD | <= 1 bbl | |
| Comment: | There is a dripping water leak at the wellhead. This was also identified in the previous inspection. Corrective action needs to be performed immediately. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | Date: 08/12/2019 |

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 689901401 | Inspection Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4971333 |