

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2019

Submitted Date:

10/24/2019

Document Number:

679705771

**FIELD INSPECTION FORM**Loc ID 316713 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10556

Name of Operator: PLUG NICKEL OIL COMPANY INC

Address: 2552 NORTH 500 EAST

City: VERNAL State: UT Zip: 84078

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Mortensen, Danny	435-790-4709	hogue@stratanet.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232270	WELL	PR	04/01/2019	OW	103-40056	UNITED 19-S-5	PR

**General Comment:**

COGCC Inspection Report Summary.

On 10-22-2019 at approximately 14:35, inspector Rick Moran, conducted a routine inspection at Plug Nickel Oil well United 19-S-5 in Rio Blanco county.

The following compliance issues were observed:

1) Missing "911" on battery sign. Photo 2. Complete by 11-24-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705771.

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Missing "911" on battery sign.	Date: 11/24/2019
Corrective Action:	Install sign to comply with Rule 210.b.	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.081190,-108.872290	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Inspector Name: Moran, Rick

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 232270	Type: WELL	API Number: 103-40056	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pump jack producing at time of inspection.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402221246	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972344">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972344</a>
679705772	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4972324</a>