

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/31/2019

Submitted Date:

11/01/2019

Document Number:

679705911**FIELD INSPECTION FORM**Loc ID 428387 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita		atlx@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428386	WELL	PR	05/14/2013	OW	103-11914	EMERALD 95X	PR
428849	WELL	PR	02/01/2019	OW	103-11922	EMERALD 96X	PR

**General Comment:**[COGCC Inspection Report Summary.](#)

On 10-31-2019 at approximately 17:20, inspector Rick Moran, conducted a follow up inspection at Chevron wells Emerald 95X & 96X in Rio Blanco county of FIR document 679705567.

The following compliance issues are uncompleted:

- 1) Fallen deadman marker. Photo 3. Complete by 10-25-2019.
- 2) Fallen well head sign. Photo 2. Complete by 10-25-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705911.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Well head sign for well Emerald 96X lying on ground.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/25/2019
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	One container of corrosion inhibitor with secondary containment.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	One fallen deadman marker.		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	10/25/2019
Type: Submersible Pump	# 2		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 428386 Type: WELL API Number: 103-11914 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on subpump.

Corrective Action:

Date:

Facility ID: 428849 Type: WELL API Number: 103-11922 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well on subpump.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass			Material Handling And Spill Prevention	Pass	

Comment: [No apparent significant soil migration, erosion, or soil movement on location.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402228650	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978195">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978195</a>
679705912	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978193">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978193</a>