

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402240839

Date Received:

11/15/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10724  
Name of Operator: NORTH SHORE EXPLORATION AND PRODUCTION LLC  
Address: 105 EDGEVIEW DR SUITE 400  
City: BROOMFIELD State: CO Zip: 80021

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Marina Ayala</u>	<u>(303)892-5616</u>	<u>marina@northshoreenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689803307

Inspection Date: 11/12/2019

FIR Submit Date: 11/14/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NORTH SHORE EXPLORATION AND PRODUCTION LLC

Company Number: 10724

Address: 105 EDGEVIEW DR SUITE 400

City: BROOMFIELD State: CO Zip: 80021

LOCATION - Location ID: 313052

Location Name: SMITH-611N94W Number: 35NESW County: MOFFAT

Qtrqtr: NESW Sec: 35 Twp: 11N Range: 94W Meridian: 6

Latitude: 40.868708 Longitude: -107.917322

FACILITY - API Number: 05-081- -00 Facility ID: 223477

Facility Name: SMITH Number: 1

Qtrqtr: NESW Sec: 35 Twp: 11N Range: 94W Meridian: 6

Latitude: 40.868708 Longitude: -107.917322

CORRECTIVE ACTIONS:

1 CA# 134511

Corrective Action: Immediately stop release. Control and contain spills/releases and clean up per Rule 906.a.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 11/14/2019

Operator Comment: The spill is cleaned up. I have photos. We are going to clean dirt in next couple of days. The source of spill has been corrected. A valve was not seating correctly resulting in high pressure gas to tank lifting some fluid out of thief hatch. The valve has been fixed. We are evaluating how to prevent this from happening again likely with some daily procedures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 134512

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 11/12/2019

Response: CA COMPLETED

Date of Completion: 11/14/2019

Operator  
Comment: The spill is cleaned up. I have photos. We are going to clean dirt in next couple of days. The source of spill has been corrected. A valve was not seating correctly resulting in high pressure gas to tank lifting some fluid out of thief hatch. The valve has been fixed. We are evaluating how to prevent this from happening again likely with some daily procedures.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: The spill is cleaned up. I have photos. We are going to clean dirt in next couple of days. The source of spill has been corrected. A valve was not seating correctly resulting in high pressure gas to tank lifting some fluid out of thief hatch. The valve has been fixed. We are evaluating how to prevent this from happening again likely with some daily procedures.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Marina Ayala

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 11/15/2019 1:21:01 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402240854	Picture
402240855	Picture
402240856	Picture

Total Attach: 3 Files