

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2019

Submitted Date:

11/09/2019

Document Number:

679706022**FIELD INSPECTION FORM**Loc ID 314277 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON USA INCCity: RANGELY State: CO Zip: 81648**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Sanford, Anita		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228162	WELL	PR	11/01/2018	OW	103-01086	WILSON CREEK UNIT 11	PR

General Comment:[COGCC Inspection Report Summary.](#)[On 11-8-2019 at approximately 14:55, inspector Rick Moran, conducted a routine inspection at Chevron well Wilson Creek Unit 11 in Rio Blanco county.](#)[The following compliance issues were observed:](#)

- [1\) Missing 911 on location sign. Photo 2. Complete by 12-8-2019.](#)
- [2\) One fallen deadman markers. Photo 3. Complete by 12-8-2019.](#)

[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)[This is a summary of inspection report 679706022.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on location sign.Corrective Action: Install sign to comply with Rule 210.b.Date: 12/08/2019Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:	<u>One fallen deadman marker.</u>		
Corrective Action:	<u>Install proper guy line markers per Rule 1003.a</u>		Date: <u>12/08/2019</u>
Type: Ancillary equipment	# 1		
Comment:	<u>Container of RE9306WCW with secondary containment.</u>		
Corrective Action:			Date:
Type: Submersible Pump	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	228162	Type:	WELL	API Number:	103-01086	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on subpump.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402235162	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984722
679706023	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4984717