

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402195481

Date Received:
10/02/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 7 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Daniel Lapp</u>	<u>970-629-9525</u>	<u>regulatory@foundationenergy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700005
Inspection Date: 09/09/2019 FIR Submit Date: 09/17/2019 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 322392

Location Name: FEDERAL-68S104W Number: 6SWSW County: _____
Qtrqtr: SWS Sec: 6 Twp: 8S Range: 104W Meridian: 6
W
Latitude: 39.391354 Longitude: -109.038624

FACILITY - API Number: 05-045-00 Facility ID: 322392

Facility Name: FEDERAL-68S104W Number: 6SWSW
Qtrqtr: SWS Sec: 6 Twp: 8S Range: 104W Meridian: 6
W
Latitude: 39.391354 Longitude: -109.038624

CORRECTIVE ACTIIONS:

1 CA# 130708

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 10/17/2019

If tank is no longer in use it is considered unused equipment. Remove tank within 90 days or repair secondary containment in 30 days.

Response: CA COMPLETED

Date of Completion: 09/27/2019

Repaired berm around tank

Operator
Comment:

COGCC Decision: Approved

COGCC
Representative:

2 CA# 130709

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.

Date: 10/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Cleaned up dirt and compressor

COGCC Decision: Approved

COGCC
Representative:

3 CA# 130710

Corrective Action: Comply with Rule 603.f .

Date: 12/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: 2 seperators located west of the location do not belong to FEM, they belong to the landowner as that is private land.

COGCC Decision: Approved

COGCC
Representative:

4 CA# 130711

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/17/2019

Operator shall provide information on if the well is shut in or temporarily abandoned.

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Gas leak repiared 9/11/19

COGCC Decision: Approved

COGCC
Representative:

5 CA# 130712

Corrective Action: Comply with Rule 603.f. (Same unused equipment on location from Inspection Doc# 675200363, 8/7/2014).

Date: 10/17/2019

Response: CA COMPLETED

Date of Completion: 09/27/2019

Operator
Comment: Removed road/location drags that were written up as unused equip.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions resolved

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: HSE Manager

Date: 10/2/2019 8:00:07 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402195481	FIR RESOLUTION SUBMITTED
402195497	Federal 6-13
402195499	Federal 6-13 2
402195500	Federal 6-13 3
402195501	Federal 6-13 4

Total Attach: 5 Files