



### SUNDRY NOTICES AND REPORTS ON WELLS

#### INSTRUCTIONS

Notice must be given to the Director, and approval obtained in advance of the time when the owner or operator expects to recomplete or abandon a well or to change plans. Within thirty (30) days after recompletion, change of plans, or remedial work, a detailed report of the work done and the results obtained shall be submitted on this form in duplicate for wells on Patented and Federal lands, and in triplicate for wells on State lands. In work that affects only rods, pumps or tubing or other routine work such as, but not limited to, cleaning out to previous total depth, no report is necessary.

|                                     |                          |                               |                                     |
|-------------------------------------|--------------------------|-------------------------------|-------------------------------------|
| Notice of Intention to Recomplete   | <input type="checkbox"/> | Report of Remedial Work       | <input type="checkbox"/>            |
| Notice of Intention to Change Plans | <input type="checkbox"/> | Report of Recompletion        | <input type="checkbox"/>            |
| Notice of Intention to Abandon Well | <input type="checkbox"/> | Other - <u>Salvage Casing</u> | <input checked="" type="checkbox"/> |

(Check appropriate space)

LEASE NAME John Thams, Jr. WELL NO. 1

FIELD Curtis WILDCAT - COUNTY Routt

LOCATION C-SW-NE Section 25 Township 6N Range 86W Meridian 6th  
 (Quarter Quarter)

2025 feet from N Section Line and 2003 feet from E Section Line  
 N or S E or W

#### (DETAILS OF WORK)

A previous request was filed for permission to abandon this well with the Production Casing in the hole. Due to the need for the casing and other considerations; We are now asking for a revocation of that request in favor of a permanent abandonment. -

#### Plugging Procedure as follows:

- Plug at 4065' w/ 10 sxs cement in 7" casing.
- Cut 7" casing at approximately 3300'
- Pull 7" casing.
- Plug at 1474' w/ 40 sxs. cement in 9-5/8" surface casing.
- Dump 5 sxs cement in top of surface casing and erect dry hole marker.

|      |                                     |
|------|-------------------------------------|
| DVR  |                                     |
| WAS  |                                     |
| TRM  |                                     |
| JAN  |                                     |
| FP   |                                     |
| JD   | <input checked="" type="checkbox"/> |
| FILE |                                     |

#### Well Data:

- TD ~~4065~~ 4811'
- PBTD 4468
- 7" casing set at 4065'
- 9-5/8" casing set at 1474'
- Top of Cement at 3400' (Temperature Survey)
- Top of Niobrara at 3679'

|          |  |
|----------|--|
| Agents:  |  |
| Bond     |  |
| Spot     |  |
| 600 ft.  |  |
| 1200 ft. |  |
| Wells    |  |
| Oil      |  |
| Gas      |  |
| Status   |  |

I/We hereby swear (or affirm) that the statements herein made are a full and correct report.

APPROVED: DEC - 1 1958 Date

Company Tennessee Gas Transmission Co. Date 11-29-58

Address Box 1772, Casper, Wyoming Phone No. 2-3501

By (Signature) Patterson Lay Title District Superintendent

Director (Signature)