

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWNE
Location # 335392



Battery sign is discolored and legibility degrading.

.

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWNE
Location # 335392



Sediment washing from around separators into roadside ditch.



Sediment washing from around separators into roadside ditch.

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWNE
Location # 335392



Sediment washing from around separators into roadside ditch.

.

TEP ROCKY MOUNTAIN LLC
PA-66S95W 33SWNE
Location # 335392



Access road into well site not being maintained.



Access road into well site not being maintained.