

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402254038

Date Received:

12/04/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Distribution, Evergreen

cogcc.evergreen@enrllc.com

Tom Beardslee

tom.beardslee@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 695101011

Inspection Date: 07/12/2019

FIR Submit Date: 07/12/2019

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC

Company Number: 10705

Address: 1801 BROADWAY SUITE 350

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308240

Location Name: GECKO-634S65W Number: 18SWNW County: LAS ANIMAS

Qtrqr: SWN Sec: 18 Twp: 34S Range: 65W Meridian: 6  
W

Latitude: 37.085850 Longitude: -104.717980

FACILITY - API Number: 05-071-00 Facility ID: 264594

Facility Name: GECKO Number: 12-18

Qtrqr: SWN Sec: 18 Twp: 34S Range: 65W Meridian: 6  
W

Latitude: 37.085850 Longitude: -104.717980

CORRECTIVE ACTIONS:

1 CA# 126985

Corrective Action: INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW IN ACCORDANCE WITH RULE 1002.f.

Date: 09/12/2019

Response: CA COMPLETED

Date of Completion: 08/28/2019

Install or repaired BMP's to prevent pooling on row and to prevent row surface from migrating

Operator  
Comment:

COGCC Decision:

COGCC  
Representative:

2 CA# 126986

Corrective Action:

INSTALL OR REPAIR BMP'S TO PREVENT STORMWATER POOLING ON ROW  
AND TO PREVENT ROW SURFACE MATERIAL FROM MIGRATING OFF OF ROW  
IN ACCORDANCE WITH RULE 1002.f.

Date: 09/12/2019

Response: CA COMPLETED

Date of Completion: 08/28/2019

Operator  
Comment:

Install or repaired BMP's to prevent pooling on row and to prevent row surface from migrating

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached Photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cheri Morgan

Signed:

Title: Regulatory Specialist

Date: 12/4/2019 3:11:55 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402254072	Gecko 12-18
-----------	-------------

Total Attach: 1 Files